Risk Assessment: Turner Centre Foyer Area

Hazard	Possible Incidents	Possible Harm	Likelihood/ Impact	Risk	Controls	Responsibility	
Staircase	Trips, Falls	Minor to moderate	C1		Steps are unobstructed.	General Manager	
Stall case		injury	CI	L	Surface is tidy and maintained.		
Trip hazards	Trips, Falls	Insignificant to minor injury	C1	L	Carpet is tidy and maintained.	General Manager	
					All cables will be taped down or secured.	Hirer	
					In low lit areas white tape will be used to draw attention to		
					these hazards.		
Electrical Equipment	Electrocution	Moderate injury	D3		All Turner Centre equipment is Test & Tagged.	General Manager	
				М	All hirers equipment brought on site needs to be Test & Tagged	Hirer	
					Noticeably damaged equipment not to be used.		
Fire	Fire	Burns, Death, Extreme Damage to property.	D4	Н	In the event of a fire, ALL WORK STOPS and Evacuation	General Manager	
					Procedures commence. Venue Personnel or hirer will ensure	/ Duty Manager	
					all are evacuated as per procedures.	/ Hirer	
Earthquake	Earthquake	Damage to building, Panic.	E5	М	In the event of an earthquake ALL WORK STOPS and Evacuation	General Manager / Duty Manager / Hirer	
					Procedures commence once shaking subsides. Venue		
					Personnel or hirer will ensure all are evacuated as per		
					procedures.		

RISK ASSESSMENT MATRIX		SEVERITY						
		1. Insignificant	2. Minor	3. Moderate	4. Major	5. Extreme		
		First Aid	Medical Treatment	Serious Injury	Multiple Serious Injuries	Fatality		
ПКЕЦНООБ	Almost Certain	Α	M	Н	С	С	С	
	Likely	В	M	Н	Н	С	С	
	Possible	Possible C L M		M	Н	Н	С	
	Unlikely D L M Rare E L L		M	Н	Н			
			L	L	L	M	M	

	RISK
C = Critical	Action Immediately
H = High	Action ASAP
M = Moderate	Managed by Controls
L= Low	Managed by routine procedures

Last revised: 8 March 2022 Page 1 of 1